

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

FLOOR CARE APPARATUS WITH MULTIPLE AGITATOR SPEEDS AND  
CONSTANT SUCTION POWER  
J. ERIK HITZELBERGER ET AL.  
380-196  
PAGE 1 OF 8





FLOOR CARE APPARATUS WITH MULTIPLE AGITATOR SPEEDS AND  
CONSTANT SUCTION POWER  
J. ERIK HITZELBERGER ET AL.  
380-196  
PAGE 3 OF 8




FIG. 3



FIG. 4a




FIG. 4b




FIG. 5

510




FIG. 6







FIG. 7







FIG. 10

FLOOR CARE APPARATUS WITH MULTIPLE AGITATOR SPEEDS AND  
CONSTANT SUCTION POWER  
J. ERIK HITZELBERGER ET AL.  
380-196  
PAGE 8 OF 8



*Fig. 11*

...ABLE COPY